
	Police Use Only			Commonwealth of Massachusetts					S	RMV Document Number				
	Date of Crash 12/1/2011	Time of Crash 17:47 24HR		y/Town ningham			hicle (Number Vehicle			ide	L	ate Police 5 ocal Police 5 BTA Police 5 ther:
		AT INTER	SECTIO	N:	<	LOCA	ATION	>		NOT A	AT IN	TERSE		The state of the s
4	Route# Direct		IMER ST	ame of Roadway	v/Street		Route#	Direction	Address #		N	lame of Roa	dway/\$t	reat
•	S	FEND		At								or	uwayrou	cer
	Route# S FENWICK ST Name of Intersecting Roadway/Street Also at Intersection with						Feet N S E W of or Exit Number						t Number	
	Route# Direc	tion	Name of	Intersecting Ro	padway/Street		F	eet N S	E W of	Route#		Intersecting		ny/Street
	Please Select C		3 1 # Occi	ipants No	on-Motorist A	Туре	14 Action	15 L	ocation	16 Condi	ition	17	Hit/Rur	Moped
	License #	18 18	3	MA DOB/A		-	M7945	E Holding			pe M	VN I	Reg State	MA 20
	Sex 1 Lic. C		Lic Restrict PAUL First	ions 1	CDL Endorsement		Year 2011 er FRAM			to the same of the			eh Config	3
1		LLIAM WELO	CH WAY	MA			ess 1 WIL		ELCH W				Mickle	
	City FRAMIN Insurance Compan Vehicle Travel Dir Citation # (If Issue	ARGONAL Rection N S	ULT	State MA 2		- Vehic Event	FRAMIN le Action Price Sequence Harmful Ever	or to Crash	22 22 22 23	21		Area Code	(Circle t	Jp to Three) 0 None 10 Undercarria
	Vial 3 Chiga-16-1						r Contributing	THE REAL PROPERTY.	1 24 Towe	24 d X 8		V.)	I I Totaled 97 Other 99 Unknown
	Name (Last First Mi		for operator an	d all occupants i	Address		DOB/Ag	Sex	26 2' Seat Safety Pos. System	Airbag Airb	29 30 ag Eject ch Code	31 32 Trap Injury Code Status	Transp.	Medical Facility
-	Operator				See Above			X	1 5	5 3	1	0 4	1	
	Please Select Or of the Following		# Occu	pants No	n-Motorist A	Гуре	14 Action	15 Lo	ocation	16 Condit	tion	" 0	Hit/Run	Moped
	icense # Lic. Cla	18 18	St Lic. Restrict	DOB/Ag	CDL		ear					R Vel		20
	DeratorOw Lust First Middle						r	Last		First		M	ficklie	
							s	tate	_ Zip _					
Vehicle Action Prior to Crash Vehicle Travel Direction: N S E W Responding to Emergency? Event Sequence 22 22 22 22 22 23 4														
	Most Ha						Harmful Event		23	24 1	_	9	1	0 None 0 Undercarriag 1 Totaled
	Driver Contributing Code 97 Other													
L	Diag								26 27	28 2	9 30	31 32	22	
	Name (Last First Mide		- 1	ist and all occup	Address		DOB/Age	Sex	Seat Safety Pos. System	Airbag Airbay	g Eject	Trap Injury Code Status	Transp. Code	Medical Facility



- Vehicle # 1 traveling south on Fenwick St.
- Vehicle # 1 turning south east onto Summer from Fenwick St.
- Vehicle # 1 struck Vehicle #2 in the intersection of Summer @ Fenwick
- Vehicle # 2 then struck Vehicle #3.
- Operator # 2 and Operator # 3 were ejected from there vehicles.

Witnesses:							
Name (Last, First, Middle)		Address			Phone #		Statement
ATOMAS ATOM	FRAMINGHAM, MA, 01701			*		1	
Property Damage:							
Owner (Last, First, Middle)	Address		Phone #	34-Type	Description of Damage	ed Property	
Truck and Bus Information:	Registration #		(From Vehic	cle Section)			35
Carrier Name					Carrier Issuing A	Authority Code	
Address			City		St	Zip	
US DOT #:	State Number	_	Issuing State	ICC #: _		Interstate	36
Cargo Body Type Code	Gross Vehicle Weight	38			39		
Trailer Reg #:	Reg Type	Reg State	Reg Year _	Tra			
Hazmat Information:	ė.						
Placard 40 Material 1 dig	it # Material Nam	e		_ Material 4 d	ligit#	. Release code	42

LESTER BAKER

282
Framingham Police
Department

12/2/2011

Police Officer Name (Please Print)


Signature

ID/Badge # Department Precinct/Barracks

Date

Narrative

See attached Narrative for statements
See attached Marrative for Statements



CDPI 11-24-00

Date of Report: | | 12/01/11 17:47 | Framingham Police Department
Framingham, MA
OFFENSE / INCIDENT REPORT CONTINUATION

Incident No:

1108263 /

Officer Narrative: BAKER, LESTER

The operator of M/V #1 for states I was turning left onto Summer St. It was clear on my left, I did not see those boys coming. The traffic was heavy I saw an opening and thought I could go. I did not see those boys coming.

Both Motorcycles had their headlights functioning. Framingham Police motorcycle's headlights run day and night, as soon as the cycle is started.

Both Officer's were wearing reflective gear over their jackets.

As MC1 and MC4 lay on the ground the lights were still on.

See RMV crash report for details of crash.

Scene was secured and held for photos, taken by Officer Studley.

Independent witness interviewed by Detective Darren Crawford.

Motorcycles towed by Exceptional Towing.

Respectfully,

Sergeant Lester Baker

Date of Report: | | 12/02/11 Framingham Police Department
Framingham, MA
SUPPLEMENT REPORT

Incident No:

1108263

Location: FENWICK ST / SUMMER ST , MA

Middlesex, MA

Officer Narrative: CRAWFORD, DARREN

Continued Investigation for Case #1108263

Interview of The Pice - 00/10/1006 - To Marketa Avenue Framingham, MA

On Friday, December 2, 2011, at approximately 1645 hours, I, Detective Darren Crawford, spoke to The Private P

On Thursday, December 1, 2011, at approximately 1745 hours, Mr. stated he was operating his Motor Vehicle, a 2006 VW Jetta on Summer Street in Framingham. Mr. stated he was travelling in a westbound direction towards Central Street. Mr. stated that the westbound traffic was backed up at the stop sign, which is located at Summer Street and Central Street. Mr. stated because of this; his vehicle was in line of traffic on Summer Street and his vehicle was stopped at the intersection of Summer Street and Fenwick Street. Mr. stated as he waited in the line of westbound traffic that was approaching the stop sign at Summer Street and Central Street, he stopped his motor vehicle just before Fenwick Street, in order to allow space at the intersection of Summer Street and Fenwick Street, for other motor vehicles to pass through the intersection.

It was at this time; Mr. ww noticed a motor vehicle, he described as "a lighter colored or grey colored Lincoln" that was stopped at the stop sign on Fenwick Street. Mr. stated that the motor vehicle, had stopped at the stop sign, and it appeared that the operator was attempting to make a left turn onto Summer Street. Mr. Dow stated that after the motor vehicle stopped, it began to proceed onto Summer Street. At this point, Mr. noticed, what at first appeared to be an approaching eastbound motor vehicle, (which he later realized as the 2 Framingham Police Motorcycles), on Summer Street, in the eastbound lane, coming from Central Street. Mr. stated he estimated that the approaching eastbound motor vehicle, (Framingham Police Motorcycles), were approximately "4 or 5 car

Investigating Officer:	Date:	Approved By:	Date:
262 CRAWFORD, DARREN	12/02/11_		
Case Status:	Approval	Status:	PAGE 1

Date of Report: |

12/02/11

Framingham Police Department
Framingham, MA
SUPPLEMENT CONTINUATION

Inqident No:

1108263 - 2

lengths" from the intersection of Fenwick Street.

Mr. Stated, that as he observed the approaching eastbound motor vehicle, (Framingham Police Motorcycles), enter the area of the intersection of Summer Street and Fenwick Street, he also observed the operator of the turning motor vehicle turning left without hesitation, onto Summer Street, despite the line of traffic in the westbound lane, which could have impeded the operator's view of the eastbound lane's traffic. Mr. Dow stated, it was at this point, he realized that he had "approximately five seconds to try to prevent, what appeared to be an impending collision." Mr. And stated that he thought about "flashing his motor vehicle's headlights" at the turning motor vehicle; to try to alert the operator of the approaching eastbound motor vehicle, but he thought that may have been more of a hindrance, in that it may have sent the wrong signal to the operator of the turning motor vehicle, as if the traffic was all clear when it was not clear.

Mr. stated at this point, he realized the approaching eastbound motor vehicle was actually two Framingham Police Motorcycles, which were riding side by side. Mr. then observed the turning motor vehicle, not slowing or stopping, as it approached the eastbound lane of Summer Street, as it appeared the operator of the turning motor vehicle did not see the Framingham Police Motorcycles. Mr. then observed the turning motor vehicle collide with the Framingham Police Motorcycle, which was on the left side of the eastbound lane of Summer Street which then collided with the Framingham Police Motorcycle on the right side of the eastbound lane of Summer Street. Mr. we stated he immediately stopped his motor vehicle and attempted to render assistance until the Police and Fire Department arrived. Our interview ended shortly afterwards.

Respectfully Submitted,

Detective Darren Crawford #262

investigating Officer:	Date:	Approved By:	Date:
_262CRAWFORD, DARREN	12/02/11		
Case Status:	Approval	Status:	
			PAGE 2