




**Crash Diagram:**



**Crash Narrative:**

On Sunday, July 2, 2017 at approximately 0600 hours, I, Sergeant Sean Riley responded to a cruiser crash at the corner of Waverly Street and Second Street. Upon arrival, I observed cruiser 963, bearing MA Police plate 790H crashed into the front of 2 Second Street. The operator of MV 1 was Officer Elizabeth Morrison who was standing outside the vehicle upon my arrival.

I asked her what happened and she stated the following at the scene. She stated she was responding to the multiple fight calls at Beaver Terrace Circle and she was driving to fast to make the turn onto Second Street from Waverly Street and couldn't control the turn and struck the house.

**Witnesses:**

Name (Last, First, Middle)	Address	Phone #	Statement
TROY DORRIS	2 SECOND ST FRAMINGHAM, MA, 01702	[REDACTED]	1

**Property Damage:**

Owner (Last, First, Middle)	Address	Phone #	41-Type	Description of Damaged Property
ALEX REALTY TRUST	21 BOSTON POSR RD E MARLBOROUGH, MA, 01752	[REDACTED]	97	BUILDING FOUNDATION, SIDING AND FRONT PORCH

**Truck and Bus Information:**

Registration # \_\_\_\_\_ (From Vehicle Section)

Carrier Name \_\_\_\_\_ Carrier Issuing Authority Code

Address \_\_\_\_\_ City \_\_\_\_\_ St \_\_\_\_\_ Zip \_\_\_\_\_

US DOT #: \_\_\_\_\_ State Number \_\_\_\_\_ Issuing State \_\_\_\_\_ ICC #: \_\_\_\_\_

Interstate  Cargo Body Type Code  GVWR/GCWR

Trailer Reg #: \_\_\_\_\_ Reg Type \_\_\_\_\_ Reg State \_\_\_\_\_ Reg Year \_\_\_\_\_ Trailer Length

**Hazmat Information:**

Placard  Material 1 digit #  Material Name \_\_\_\_\_ Material 4 digit # \_\_\_\_\_ Release code

SEAN RILEY

277

Framingham Police  
Department

7/2/2017

Police Officer Name (Please Print)

Signature

ID/Badge #

Department

Precinct/Barracks

Date

Narrative

[REDACTED] Framingham Fire Ladder 1 was also on scene and stated the foundation damage caused by the crash didn't appear to be a safety concern.

Photos of the scene were taken by me, Sergeant Riley using Patrol Camera #1 and later by Officer Bufford of the Framingham Police Department Prints and Photos Division.

The witness, Troy Dorris - [REDACTED] who lives on the second floor of 2 Second Street stated the following. Troy stated he was in his bedroom which overlooks Second Street and he could hear a car speeding on Waverly Street. He stated he then heard the screeching of tires and then a crash. I asked if he heard sirens on, he stated "no". He said he didn't know it was a police car until he went outside.

[REDACTED]

[REDACTED]

Based on initial findings, Officer Morrison was found at fault for the accident and issued MA Uniform Citation [REDACTED]

[REDACTED]

The above narrative is a brief statement of facts for the crash report only. Full investigative narrative will be submitted separately.

Respectfully Submitted,

Sergeant Sean Riley #277